5

## **ABSTRACT**

## **REFINING FERROALLOYS**

A method of refining a ferroalloy includes the step of blowing molecular oxygen or a gas mixture including molecular oxygen into a melt of the ferroalloy. A metallurgically acceptable particulate material is introduced from above into the melt. The particulate material is carried into the melt in a first supersonic gas jet which travels to the melt shrouded by a second gas jet.

15

10